

07/10/23 INSPECTION PHOTOS  
BIG RUN PRODUCTION ARGENTA 18  
and ARGENTA 19  
API # 007-06049 and 007-06094





DETERIRATED LABELS, OPEING IN TOP  
OF BARREL



WILDLIFE SCREEN COLLAPSED, WASTE  
EXPOSED





CHEMICAL SYSTEM IN DISARRAY, NO  
BRADENHEAD ACCESS





DETERIORATED LABELS, OPENING IN  
TOP OF BARREL



UNUSED EQUIPMENT, LANDOWNER  
STORAGE ENCROACHING ON  
PRODUCTION AREA







UNUSED NON-SERVICABLE  
EQUIPMENT







DRY COMBUSTIBLE VEGETATION  
NEAR EQUIPMENT





UNMARKED RIG ANCHORS





NO BRADENHEAD ACCESS