

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/13/2023

Submitted Date:

07/13/2023

Document Number:

701007166

**FIELD INSPECTION FORM**

Loc ID 321823 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 37230  
Name of Operator: HALDE OIL INC  
Address: 46321 HWY 24  
City: BURLINGTON State: CO Zip: 80807

**Findings:**

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Halde, Kerry	719-346-0653	haldeoil@hotmail.com	
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208128	WELL	PR	05/21/1996	GW	017-07063	NORRENE 13-2 1	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign by meter run		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by compressor		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by tank		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>		
Comment:	<input style="width: 500px; height: 20px;" type="text"/>	
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>	Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator east of wellhead		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter run south of wellhead on north side of CR Z		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 114		
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		

Comment:	Gas scrubber, chemical tank, telemetry equipment at meter run, propane tanks, cathodic generator and rectifier		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		38.948930,-102.201620

Comment:	Production tank moved from north side of CR Z to wellhead location		
Corrective Action:		Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Berms need maintenance for capacity		
Corrective Action:		Date:	

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 208128 Type: WELL API Number: 017-07063 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Meter run is 1650' SSW of wellhead](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT