

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Northwest access road to location



Northwest entrance to location

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Southeast access road to location



Southeast entrance to location

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Soil stain in June



Soil stain in July

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Soil staining.



Area of soil staining

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Soil staining off edge of location.



Erosion from location. Debris

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Erosion from location. Debris



Erosion from location

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



No berm. Location slopes downhill.



Erosion leaving location

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Erosion from location



Erosion from location

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Debris



Debris

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Debris



Debris

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Debris



Debris

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Debris



Debris

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Location from Northwest corner

Location from Northeast corner

**CALCO dba Callister Co.
Callister-Government 3
Loc ID: 314355**



Location from Southwest corner



Location from Southeast corner