

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 533-19 Pad

Location ID: 335368



Photo # 2942 From entrance to location



Photo # 2943 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 533-19 Pad

Location ID: 335368



Photo # 2944 Location



Photo # 2945 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 533-19 Pad

Location ID: 335368



Photo # 2949 Debris (S/SE corner of location)



Photo # 2951 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 533-19 Pad

Location ID: 335368



Photo # 2953 Unmarked deadman #1



Photo # 2954 Same unmarked deadman from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 533-19 Pad

Location ID: 335368



Photo # 2960 Unmarked deadman #2



Photo # 2961 Same unmarked deadman from a different angle