

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad
Location # 324102



**Location Overview: Location is within High Priority/Density
Habitat areas & in close proximity to Bald Eagle Roost sites.
All drainages contribute to the Colorado River.
Section/Township/Range: 20 6S94W**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad
Location # 324102



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad
Location # 324102



Photo # 2890 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)



Photo # 2891 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad
Location # 324102



Photo # 2892 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)



Photo # 2893 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad
Location # 324102



Photo # 2894 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)



Photo # 2895 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad
Location # 324102



Photo # 2897 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)



Photo # 2899 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad
Location # 324102



Photo # 2900 Erosion & transport of sediment (edge of lease road, approximately 1/10th of a mile from location)