

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102



Photo # 2863 From entrance to location



Photo # 2864 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102



Photo # 2866 Location

Photo # 2867 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102



Photo # 2868 Location



Photo # 2869 Flowline heating insulation open ended

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102




Photo # 2870 Flowline heating insulation open ended

