

Inspection Photos
Location Name: Brophy T 46-15
Location ID: 125-07126




1. Rig sign at CR 57 and access road.



2. View of Work Over Rig approaching location.

Inspection Photos
Location Name: Brophy T 46-15
Location ID: 125-07126



Well sign at well site.



View of well with Blow Out Preventer installed for well work.

Inspection Photos
Location Name: Brophy T 46-15
Location ID: 125-07126



5. View of rear of Pump Jack and electric Prime Mover.



6. Pump Jack power and control panel.

Inspection Photos
Location Name: Brophy T 46-15
Location ID: 125-07126



7. One of four anchors/deadmen marked and in use.



8. Well sign located at remote Gas Meter Run.

Inspection Photos
Location Name: Brophy T 46-15
Location ID: 125-07126



9. View of remote Meter House at CR 57.



10. View if Gas Meter Run inside Meter House.