



Inspection Photos
Location Name: Bledsoe 5-17-3-43
Location ID: 125-09180



1. Well sign.



2. View of wellhead, concrete slab, and meter/separator shed.

Inspection Photos
Location Name: Bledsoe 5-17-3-43
Location ID: 125-09180



3. View of Vertical Separator inside shed.



4. View of Gas Meter Run inside shed.

Inspection Photos
Location Name: Bledsoe 5-17-3-43
Location ID: 125-09180



5. Charter inside Meter Box dated 12-2-22 at time of inspection.



6. Downed Deadman Marker.