


Inspection Photos
Location Name: Bledsoe 4-17-3-43
Location ID: 125-09109



1. Well sign located inside stock panel fencing.



2. Wellhead and tree. Note vegetation growth inside fencing.

Inspection Photos
Location Name: Bledsoe 4-17-3-43
Location ID: 125-09109



3. View of Gas Meter Run and Vertical Separator inside Shed.



4. Gas Meter Chart that was in Meter Box at time of inspection.