

Inspection Photos  
Location Name: Bledsoe 11-18-3-43  
Location ID: 125-09119



1. Well sign.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Bledsoe 11-18-3-43**  
**Location ID: 125-09119**



**3. Tubing appears to be pulled above well and Ball Valve at top.**




**4. View of Pump Jack. Note vegetation growing inside fencing.**



**Inspection Photos**  
**Location Name: Bledsoe 11-18-3-43**  
**Location ID: 125-09119**



**5. View of Gas Meter Run and Vertical Separator inside shed.**



**6. Chart in Meter Box dated 12-2-22.**