

Inspection Photos

7/10/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421



Photo 1: Photo taken from the access road ~ ½ mile south of the Location. Photo shows berms remain along the southern perimeter of the Location. Location has not been reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421



Photo 2: Photo taken from the west of the Location. Photo shows fill slopes remain. Location has not been recontoured/regraded and reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421



Photo 3: Photos 3-4 taken from the east end of the Location. Photos provide an overview from south, southwest, northwest to north. Location has not been recontoured/regraded and reclaimed; topsoil has not been replaced; compaction alleviation not performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421



Photo 5: Fill slopes on the Location; Location has not been recontoured/regraded and reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421



Photo 6: Soils stockpiled on the southern perimeter of the Location has not been replaced.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 324421



Photo 3: Photo left taken from the central areas of the disturbed Location. Photo shows topsoil has not been replaced. Photo right is an example of the vegetation within the adjacent reference area for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources