

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3139 From entrance to location



Photo # 3140 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3141 Location

Photo # 3142 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3143 Location



Photo # 3144 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 4230 From Inspection 708900232 conducted on 04/04/2023 Tank label has incorrect information

Photo # 3145 Tank label has incorrect information/capacity incorrect

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3154 Debris/Hazard - broken deadman/anchor sticking up out of the ground



Photo # 3155 Debris/Hazard - same broken deadman/anchor sticking up out of the ground from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3158 Unmarked deadman/anchor



Photo # 3157 Same unmarked deadman/anchor from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3156 Debris