

Inspection Photos
Location Name: Antelope 42-19 RTB
Location ID: 418214



Photo 1 – Tank Battery



Photo 2 – Tumbleweed Debris

Inspection Photos
Location Name: Antelope 42-19 RTB
Location ID: 418214



Photo 3 – NE 300 NFPA Label



Photo 4 – Tank Battery Signs



Inspection Photos
Location Name: Antelope 42-19 RTB
Location ID: 418214



Photo 5 – Tank Battery Signs



Photo 6 – ECD

Inspection Photos
Location Name: Antelope 42-19 RTB
Location ID: 418214




Photo 7 – Unmarked Risers



Photo 8 – Separators – Tumbleweed Debris

Inspection Photos
Location Name: Antelope 42-19 RTB
Location ID: 418214




Photo 9 – Unmarked Riser under Tumbleweed Debris