

Inspection Photos

Location Name: Orr USX/A03-15D

Location ID: 305789



Photo #1

Orr USX A03-15D (123-34031) Wellsite

Plugged & Abandoned | PA

Plugging Ops: Cementing: Balanced plug



Photo #2

Orr USX A03-15D Wellsite

Plugged & Abandoned | PA

Plugging Ops: Cementing: Balanced plug

Site safety signage

Inspection Photos

Location Name: Orr USX/A03-15D
Location ID: 305789

tools stop work author: **the human energy company**

job safety analysis (JSA) form
roles, contingency and response

rockies business unit (RSU) 870.454.1111

Date and time: 7/18/23 6:26 AM
Location Name: ORR USX A03-15D
In Charge: JASON HARRIS
Phone Number: 970-304-5286
Job Description: TO, MACHINE T14 MALFUNCTION RESOLVED

In Case of Emergency Call 911 for Life
PC: Personal Number (720) 343-7301
24 Hour GC Contact: 970-304-5286

WEATHER: 75° 66%
2 mph
Clear

Dial 911 for Emergencies
NEAREST MEDICAL CENTER Immediate Medical Attention:
25 Northern Colorado Medical Center (970) 810-4371 Greeley, CO
24 Huron Valley Medical Center (970) 496-8000 Fort Collins, CO
24 Sterling Regional Medical Center (970) 422-0192 Sterling, CO
24 Other:

Location Sketch (sketch as "hand-drawn")
* Placed Area
* Work Area
* Critical Area
* Critical Distance (Elevations)
* Other Lines
* Other Location
* Other Distance (Elevations)

SMOBS Review: ☒ NO SMOBS
Identify Procedure (check "X")
X SOP (Site Operating Procedure)
X SOP Title: P3A
☐ GRS (Quick Reference Guide)
☐ Other:
Location-Specific Notes:
AS, HARRIS, T14 p
MALFUNCTIONS

Work Crew Sign-off (please print name)
Every person that could be impacted by this job must LEGIBLY sign-in including their COMPANY NAME.
Do not sign off if you are not a trained and authorized person. Do not sign off if you are not a trained and authorized person. Do not sign off if you are not a trained and authorized person.

Person in Charge (print name)
Jason Harris

Colorado Energy & Carbon Management Commission
Weld County
+40.513717, 104.532951
42° NE
2023-07-18 16:12



Photo #3
Orr USX A03-15D Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Balanced plug
JSA: 2023-07-18

Photo #4
Orr USX A03-15D Wellsite entrance
Plugged & Abandoned | PA
Plugging Ops: Cementing: Balanced plug
Wellsite entrance sign