

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 307213

Inspection Document #: 701900963

NESW Section 25 T5N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ryan 23-25 U
Location ID: 307213



Photo 1. 2023 aerial imagery of the well pad and access road (north is up).
Note: tank battery highlighted in blue is associated with the Ryan 25-BU well
API # 069-06334.

Inspection Photos
Location Name: Ryan 23-25 U
Location ID:307213



Photo 2. Overview photos of both the access road (left) and well pad (right) taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Ryan 23-25 U
Location ID:307213



Photo 3. Close up overview photo of the well pad taken at ground level from the northern edge facing south. Note: well pad falls under irrigation pivot staging location and is dominated by rocky mountain bee plant.

