

Final Reclamation Inspection

July 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323063

Inspection Document #: 701900966

SWSW Section 32 T5N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Parish 32-2
Location ID: 323063



Photo 1. 2023 aerial imagery of the well pad and tank battery (north is up). Note: well pad falls within a storage unit lot.

Inspection Photos
Location Name: Parish 32-2
Location ID: 323063



Photo 2. Overview photo of the well pad taken at ground level from the northern edge facing south.

Inspection Photos
Location Name: Parish 32-2
Location ID: 323063



Photo 3. Overview photo of the tank battery taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Parish 32-2
Location ID: 323063



Photo 4. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Parish 32-2
Location ID: 323063



Photo 5. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery is dominated by a weedy annual vegetation, cheatgrass.