

Inspection Photos
Location Name: Orr USX/A03-15D
Location ID: 305789



Photo #1

Orr USX A03-15D (123-34031) Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Surface plug



Photo #2

Orr USX A03-15D Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Surface plug
Site safety signage; prior photo

Inspection Photos

Location Name: Orr USX/A03-15D
Location ID: 305789

Photo #3

Orr USX A03-15D Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Surface plug
JSA: 2023-07-19



Photo #4

Orr USX A03-15D Wellsite entrance
Plugged & Abandoned | PA
Plugging Ops: Cementing: Surface plug
Wellsite entrance sign; prior photo



Inspection Photos

Location Name: Orr USX/A03-15D

Location ID: 305789



Photo #5

Orr USX A03-15D Wellsite

Plugged & Abandoned | PA

Plugging Ops: Cementing: Surface plug

Cement to surface; Time: 16:46; Operator photo



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources