

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SWNE

Location ID: 334659

Date: 7/7/2023



SW Corner of Location – Photo #05071



NW Corner of Location – Photo #05072

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SWNE

Location ID: 334659

Date: 7/7/2023



NE Corner of Location – Photo #05073



SE Corner of Location – Photo #05074

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SWNE

Location ID: 334659

Date: 7/7/2023



Wellheads – Photo #05075



Separators – Photo #05078

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SWNE

Location ID: 334659

Date: 7/7/2023



Tank Battery – Photo #05079