

Final Reclamation and Stormwater Inspection

Date: 07/19/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 326748

Inspection Document #: 708200397

Weld County, CO

SWNW Section 11 T8N R58W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Lilli Unit 5-11
Location ID: 326748



Photo 1. Equipment and debris remain on location and will need to be removed.

Inspection Photos
Location Name: Lilli Unit 5-11
Location ID: 326748



Photo 2. Facing south towards the location. The location appears to be progressing towards Rule 1004 standards with evidence of desirable perennial vegetative cover.

Inspection Photos
Location Name: Lilli Unit 5-11
Location ID: 326748



Photo 3. Facing northwest from the southern portion of the location; see comments in Photo 2.

Inspection Photos
Location Name: Lilli Unit 5-11
Location ID: 326748



Photo 4. Facing east from the western portion of the location; see comments in Photo 2.

Inspection Photos
Location Name: Lilli Unit 5-11
Location ID: 326748



Photo 5. Undesirable vegetation (e.g. CO List C Noxious Weed- cheatgrass) will need to be managed for in the future as the plant has already begun to drop seed.