

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 1 Location.



Photo 2 TB/signs

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 3 TB.



Photo 4 LACT

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 5 FWKO.



Photo 6 Compressor.

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 7 Horizontal Heated separators.



Photo 8 Horizontal Heated separators.

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 9 ECD.



Photo 10 VRU x 3.

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 11 Stained soil around the east VRU.



Photo 12 Stained soil around the east VRU.

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 13 Stained soil around the east VRU.



Photo 14 Electric panels and transformers.

Inspection Photos
Location Name: Dolph Tank Battery 1N-1HZ
Location ID: 436963



Photo 15 VRT.



Photo 16 Gas Meter Run.