


Inspection Photos
Location Name: Garrett 6-33-6-45
API Number: 095-06113



1. Well sign on Meter Shed door.



2. View of Wellhead. Note staining on ground around wellhead.

Inspection Photos
Location Name: Garrett 6-33-6-45
API Number: 095-06113




3. Closer view of Wellhead ground area.



4. View of Gas Meter Run inside Meter Shed.

Inspection Photos
Location Name: Garrett 6-33-6-45
API Number: 095-06113



5. View of Chart inside Meter Box dated 12-1-22.

Ominex Meter Test Report

Well Name Garrett 6-33-6-45 Date 7-14-20

Diff. Range 0 to 100
 Static Range 0 to 150
 Temp Average 60

Piston .250

| Differential | | | Static | | |
|--------------|-------|------|--------------|-------|--------------|
| Chart Read | Found | Left | Chart Read | Found | Left |
| 0 | 0 | 0 | 0 | 0 | 0 |
| 100 | 100 | 100 | 150 (250) | 150 | 150 (250) |
| 50 | 50 | 50 | 75 (150) 112 | 75 | 75 (150) 112 |
| 0 | 0 | 0 | 0 | 0 | 0 |

Inspector [Signature]

2023.07.19 17:07

6. View of Meter Calibration/Test Log dated 7-14-20.

Inspection Photos
Location Name: Garrett 6-33-6-45
API Number: 095-06113



7. View of unused equipment; Solar Panel, Polish Rod, Tubing Sub. Note Dried grass inside fencing.



8. Unused equipment. Note grass growth inside fencing.