

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAMM CREEK FEDERAL 12-33 Pad

Location ID: 334696



Photo # 3800 From entrance to location



Photo # 3801 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAMM CREEK FEDERAL 12-33 Pad

Location ID: 334696



Photo # 3802 Location



Photo # 3803 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAMM CREEK FEDERAL 12-33 Pad

Location ID: 334696



Photo # 3804 Location



Photo # 3806 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAMM CREEK FEDERAL 12-33 Pad

Location ID: 334696



Photo # 3809 Location



Photo # 3810 Unused equipment – ECD is disconnected


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAMM CREEK FEDERAL 12-33 Pad

Location ID: 334696



Photo # 3812 Unused equipment – ECD is disconnected



**Photo from Inspection 700704355 conducted on 06/27/2022
ECD is disconnected**