

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC P32 Pad**  
**Location #: 334836**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas & within close  
proximity to NSO Habitat area & Bald Eagle Roost site.  
Location is approximately 357 yards from Mamm Creek.  
Section/Township/Range: 32 6S92W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC P32 Pad**  
**Location #: 334836**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC P32 Pad**  
**Location #: 334836**



**Photo # 3791 Culvert needs maintenance**



**Photo # 3792 Failure to minimize erosion & transport of sediment/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC P32 Pad**  
**Location #: 334836**



**Photo # 3793 Failure to minimize erosion & transport of sediment/sediment choking off vegetation**



**Photo # 3795 Failure to minimize erosion & transport of sediment/sediment choking off vegetation**