

Inspection Photos
Location Name: Chesnut/SW-22
Location ID: 418285



Photo #1
Chesnut 22BD (123-31889) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 20 yds.



Photo #2
Chesnut 22PD, 22KD, 22BD, 22OD, 22-23, 22-24
Battery site
Abandoned: ALL Equipment Removed