

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Location is
approximately 487 yards from Middle Mamm Creek.
Section/Township/Range: 19 7S92W**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



Photo # 3977 Rill erosion & transport of sediment (S/SE area of pad near entrance to location)



Photo # 3980 Rill erosion & transport of sediment (S/SE area of pad near entrance to location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



Photo # 3989 Erosion & transport of sediment on lease road



Photo # 3990 Erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



Photo # 3991 Erosion & transport of sediment on lease road



Photo # 3993 Erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



Photo # 3988 Erosion & transport of sediment on lease road