


Inspection Photos

Location Name: Lueking 42-19X 5N 46W

API Number: 125-10822



1. Well sign on Meter Shed door.



2. View of Wellhead.

Inspection Photos
Location Name: Lueking 42-19X 5N 46W
API Number: 125-10822



3. Location overview.



4. View of Electric Motor and Chemical Tank at Pump Jack.

Inspection Photos
Location Name: Lueking 42-19X 5N 46W
API Number: 125-10822



5. Meter Shed.



6. Gas Meter Run inside Meter Shed.

Inspection Photos
Location Name: Lueking 42-19X 5N 46W
API Number: 125-10822



7. View of rig anchor with downed Anchor Marker.



8. View of unmarked rig anchor.

Inspection Photos
Location Name: Lueking 42-19X 5N 46W
API Number: 125-10822



9. View of marked rig anchor.



10. View of unmarked rig anchor.