

Inspection Photos  
Location Name: Lueking 3-19  
API Number: 125-06308



1. Well sig on Meter Shed.



2. View of Wellhead.

Inspection Photos  
Location Name: Lueking 3-19  
API Number: 125-06308



3. Pump Jack.



4. View of Prime Mover with drive belts disconnected.

**Inspection Photos**  
**Location Name: Lueking 3-19**  
**API Number: 125-06308**



**5. One of the four concrete pillars at well site.**



**6. Gas Meter Run inside Meter Shed.**