

Inspection Photos
Location Name: Lueking 41-19 5N 46W
API Number: 125-11924



1. Well sign at well location.



2. View of Wellhead.

Inspection Photos
Location Name: Lueking 41-19 5N 46W
API Number: 125-11924



3. Progressive Cavity on Wellhead.



4. Well site location overview

Inspection Photos
Location Name: Lueking 41-19 5N 46W
API Number: 125-11924



5. Well sign at Gas Meter Run at well location.



6. Gas Meter Run inside Meter Shed.

Inspection Photos
Location Name: Lueking 41-19 5N 46W
API Number: 125-11924



7. Overview of Gas Meter site.



8. One of three marked rig anchors. Unable to locate fourth.