

Final Reclamation Inspection

July 15 2023

Operator: PDC ENERGY INC - 69175

Location ID: 327207

Inspection Document #: 701900999

NESW Section 30 T4N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Frank 1
Location ID: 327207




Photo 1. 2023 aerial imagery of the well pad and access road (north is up). Note: tank battery indicated by blue arrow has been absorbed by the Ram Land production facility (could not locate location ID number)

Inspection Photos
Location Name: Frank 1
Location ID: 327207



Photo 2. Overview photo of the well pad taken at ground level from the northern edge facing southeast.

Inspection Photos
Location Name: Frank 1
Location ID: 327207



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Frank 1
Location ID: 327207



07/15/2023 16:05



07/15/2023 16:05

Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent reference area (see photo 5).

Inspection Photos
Location Name: Frank 1
Location ID: 327207



07/15/2023 16:11

Photo 5. Reference area.

Inspection Photos
Location Name: Frank 1
Location ID: 327207



Photo 6. Overview photos of the well pad access road. Note: photo shows that operator has performed final reclamation activities with evidence of drill rows and straw crimped mulch. Site will remain in-process until uniform plant cover of at least 80% of the reference area is achieved.



Photo 7. Overview photo of the tank battery. Note: absorbed by active Ram Land production facility.