

Final Reclamation and Stormwater Inspection

Date: 07/26/2023

Operator: MARKUS PRODUCTION INC - 53790

Location ID: 313907

Inspection Document #: 708200411

Morgan County, CO

NESE Section 30 T5N R60W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Welker 43-30
Location ID: 313907



Photo 1. The former well location appears to be progressing towards Rule 1004 standards with evidence of the reclaimed areas reflective of the adjacent areas.

Inspection Photos
Location Name: Welker 43-30
Location ID: 313907



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Welker 43-30
Location ID: 313907



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Welker 43-30
Location ID: 313907



Photo 4. See comments in Photo 1.



Photo 5. Partially buried flowline observed adjacent to an access road, running from the well location to the former tank battery location. This equipment will need to be properly removed. Refer to subsequent photos for aerial imagery.

Inspection Photos
Location Name: Welker 43-30
Location ID: 313907



Photo 5. Google Earth aerial imagery taken circa 06/2016 illustrates the flowline position and the former tank battery location.

Inspection Photos
Location Name: Welker 43-30
Location ID: 313907



Photo 6. Google Earth aerial imagery taken circa 03/2020, illustrating that the former tank battery location does not appear reflective of adjacent reference areas as it is being used as storage. The tank battery location will need to be reclaimed per Rule 1004 standards.