

Inspection Photos
Location Name: Bledsoe 9-19-5-44
API Number: 125-09454



1. Well sign leaned against meter shed.



2. Well sign.

Inspection Photos
Location Name: Bledsoe 9-19-5-44
API Number: 125-09454



3. View of wellhead. Note debris and stained soils at well.




4. Concrete pad with accumulated lube oil on pad and surrounding soils.

Inspection Photos
Location Name: Bledsoe 9-19-5-44
API Number: 125-09454



5. Chart in Meter Box at time of inspection.



6. Meter calibration/test log inside meter shed.

Inspection Photos
Location Name: Bledsoe 9-19-5-44
API Number: 125-09454



7. Location overview. Note debris onsite.



8. Cattle guard at access entrance. Roadside is washing down slope.

Inspection Photos
Location Name: Bledsoe 9-19-5-44
API Number: 125-09454



9. Access road at entrance to location.



10. Access road erosion gully.

Inspection Photos
Location Name: Bledsoe 9-19-5-44
API Number: 125-09454



11. Access road.



Access road.