

**Inspection Photos**  
**Location Name: Coulter 9-12**  
**Location ID: 305770**




**Photo 1 Location**



**Photo 2 WH sign.**



**Inspection Photos**  
**Location Name: Coulter 9-12**  
**Location ID: 305770**



**Photo 3 WH**



**Photo 4 Fugitive Gas Combustion device.**



**Inspection Photos**  
**Location Name: Coulter 9-12**  
**Location ID: 305770**



**Photo 5 Tall undesirable plant species (vegetation) growing around the location ROW.**



**Photo 6 Tall undesirable plant species (vegetation) growing around the location ROW.**



**Inspection Photos**  
**Location Name: Coulter 9-12**  
**Location ID: 305770**



**Photo 7 Tall undesirable plant species (vegetation) growing around the location ROW.**



**Photo 8 Tall undesirable plant species (vegetation) growing around the location ROW.**