

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06A Pad

Location ID: 450791

Date: 8/1/2023



NW Corner of Location – Photo #05332



SW Corner of Location – Photo #05333

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06A Pad

Location ID: 450791

Date: 8/1/2023



SW Corner of Location – Photo #05335



SE Corner of Location – Photo #05336

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06A Pad

Location ID: 450791

Date: 8/1/2023



Wellheads – Photo #05337



Separators – Photo #05338

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06A Pad

Location ID: 450791

Date: 8/1/2023



Tank Battery – Photo #05339



Wildlife Entry Hazard – Photo #05341



Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06A Pad

Location ID: 450791

Date: 8/1/2023



Wildlife Entry Hazard – Photo #05342



Storage of Supplies/Equipment – Photo #05340

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06A Pad

Location ID: 450791

Date: 8/1/2023



Storage of Supplies/Equipment – Photo #05343