

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06 Pad

Location ID: 334504

Date: 8/1/2023



**West Entrance to Location – Photo #05346**



**Wellheads – Photo #05347**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06 Pad

Location ID: 334504

Date: 8/1/2023



Separators – Photo #05348



Tank Battery – Photo #05349





## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-06 Pad

Location ID: 334504

Date: 8/1/2023



**Wildlife Entry Hazard – Photo #05350**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources