

Construction & Stormwater Inspection

July 26, 2023

Operator: Crestone Peak, # 10633

Location ID: 447713

Inspection Document # 709400436

Adams, CO

SESE, 21 3S65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Schuh 3-65
Location ID: 457713



Photo 1. Photo of location sign on site.



Photo 2. Photo of tank battery.

Inspection Photos

Location Name: Schuh 3-65

Location ID: 457713



Photo 3. Photo of weeds on ste.



Photo 4. See photo 3 comments.