

# Interim & Stormwater Inspection

July 26, 2023

Operator: Crestone Peak, # 10633

Location ID: 435177

Inspection Document # 709400444

Adams, CO

NWNW, 26 3S65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: Reserve 3-65

Location ID: 435177



Photo 1. Photo of location sign on site.



Photo 2. Photo of tank battery.

Inspection Photos

Location Name: Reserve 3-65

Location ID: 435177



**Photo 3.** Photo of weeds on site.



**Photo 4.** Photo of weeds on site.