

Inspection Photos

Location Name: LARAMIE ENERGY LLC, McDaniel/11-10 Pad

Location ID: 334508

Date: 8/2/2023



NE Entrance Corner of Location – Photo #05353



NW Corner of Location – Photo #05354

Inspection Photos

Location Name: LARAMIE ENERGY LLC, McDaniel/11-10 Pad

Location ID: 334508

Date: 8/2/2023



SW Corner of Location – Photo #05361



SE Corner of Location – Photo #05362

Inspection Photos

Location Name: LARAMIE ENERGY LLC, McDaniel/11-10 Pad

Location ID: 334508

Date: 8/2/2023



Wellheads – Photo #05360



Wellheads – Photo #05355

Inspection Photos

Location Name: LARAMIE ENERGY LLC, McDaniel/11-10 Pad

Location ID: 334508

Date: 8/2/2023



Separators – Photo #05357



Tank Battery – Photo #05365

Inspection Photos

Location Name: LARAMIE ENERGY LLC, McDaniel/11-10 Pad

Location ID: 334508

Date: 8/2/2023



Location Lacks Stabilization – Photo #05363



Location Lacks Stabilization – Photo #05364

Inspection Photos

Location Name: LARAMIE ENERGY LLC, McDaniel/11-10 Pad

Location ID: 334508

Date: 8/2/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05366**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05367**