

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location ID: 452797

Date: 8/2/2023



SW Entrance to Location – Photo #05377



SE Corner of Location – Photo #05378

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location ID: 452797

Date: 8/2/2023



NE Corner of Location – Photo #05380



NW Corner of Location – Photo #05382



## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location ID: 452797

Date: 8/2/2023



Wellheads – Photo #05379



Separators – Photo #05383



## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location ID: 452797

Date: 8/2/2023



**Tank Battery – Photo #05385**



**Location Lacks Stabilization – Photo #05386**



## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location ID: 452797

Date: 8/2/2023



**Location Lacks Stabilization – Photo #05387**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05388**