

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/13-11 Pad

Location ID: 334546

Date: 8/2/2023



NE Corner of Location – Photo #05390



SE Corner of Location – Photo #05392

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/13-11 Pad

Location ID: 334546

Date: 8/2/2023



SW Corner of Location – Photo #05393



NW Corner of Location – Photo #05395

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/13-11 Pad

Location ID: 334546

Date: 8/2/2023



Wellheads – Photo #05396



Wellheads – Photo #05399

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/13-11 Pad

Location ID: 334546

Date: 8/2/2023



Separators – Photo #05397



Separators – Photo #05400

# Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/13-11 Pad

Location ID: 334546

Date: 8/2/2023



Tank Battery – Photo #05403

Tank Battery – Photo #05402

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/13-11 Pad

Location ID: 334546

Date: 8/2/2023



Stored Equipment/Supplies – Photo #05404



Stored Equipment/Supplies – Photo #05406

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/13-11 Pad

Location ID: 334546

Date: 8/2/2023



**Location Lacks Stabilization – Photo #05401**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05408**