

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gipp/13-9 Pad

Location ID: 334498

Date: 8/2/2023



Entrance to Location – Photo #05411



East Exit of Location – Photo #05410

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gipp/13-9 Pad

Location ID: 334498

Date: 8/2/2023



Wellheads – Photo #05412



Separators – Photo #05413



## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gipp/13-9 Pad

Location ID: 334498

Date: 8/2/2023



**Tank Battery – Photo #05414**



**Location Lacks Stabilization – Photo #05416**



## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gipp/13-9 Pad

Location ID: 334498

Date: 8/2/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05417**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05418**