

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 8/3/2023



South Entrance to Location – Photo #05460

East Corner of Location – Photo #05461

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 8/3/2023



North Corner of Location – Photo #05462



West Corner of Location – Photo #05464

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 8/3/2023



Aug 3, 2023 at 14:06:49



Aug 3, 2023 at 14:07:11

Wellheads – Photo #05465

Wellheads – Photo #05466

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 8/3/2023



Separators – Photo #05468



Tank Battery – Photo #05470

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 8/3/2023



ECD – Photo #05469



Location Lacks Stabilization – Photo #05471

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 8/3/2023



Location Lacks Stabilization – Photo #05472

Location Lacks Stabilization – Photo #05473

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 8/3/2023



Location Lacks Stabilization – Photo #05474

**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05475**