

Inspection Photos
Location Name: Bledsoe 4-26-5-45
API Number: 125-09611



1. Well sign at well location. Operator emergency contact number posted on sign does not work.



2. View of wellhead.

Inspection Photos
Location Name: Bledsoe 4-26-5-45
API Number: 125-09611



3. View of well location with tubing joint bent over.



4. Closer view of bent tubing joint.

Inspection Photos
Location Name: Bledsoe 4-26-5-45
API Number: 125-09611



5. View of damaged fencing crushed by tubing being forced over by irrigation pivot arm.



6. Production related debris and cement pad inside fencing.

Inspection Photos
Location Name: Bledsoe 4-26-5-45
API Number: 125-09611



7. View of remote Meter Shed. No well sign at site. Note vegetation growth.



8. View of Chart inside Meter Box at time of inspection.

Inspection Photos
Location Name: Bledsoe 4-26-5-45
API Number: 125-09611

Omimex Meter Test Report

Well Name Bledsoe 4-26-5-45 Date 7-17-26

Diff. Range 0 to 100 Plate 250

Static Range 0 to 150

Temp Average 60

Differential			Static		
Chart Read	Found	Left	Chart Read	Found	Left
0	0	0	0	0	0
100	100	100	150 (250)	150	150 (250)
50	50	50	75 (150) (125)	75	75 (150) (125)
0	0	0	0	0	0

Inspector [Signature]

2023.08.02 11:37

9. View of Meter Calibration/Test Log inside Meter Shed at time of inspection.



10. Pig Station on N side of Meter Shed. Note vegetation growth.