

Inspection Photos

Location Name: NAKAGAWA PM B-65N64W/13NWSE

Location ID: 327101



Photo #1

Nakagawa PM B 13-10 (123-14157) Wellsite

Shut-In | SI



Photo #2

Nakagawa PM B 13-10, B 13-16 Battery site

Inactive | Shut-down

Formerly served:

Nakagawa B13-9 ;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NAKAGAWA PM B-65N64W/13NWSE

Location ID: 327101



Photo #3

Nakagawa PM B 13-10, B 13-16 Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #4

Nakagawa PM B 13-10, B 13-16 Battery site

Inactive | Shut-down

Separator(s), ECD(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NAKAGAWA PM B-65N64W/13NWSE

Location ID: 327101



Photo #5

Nakagawa PM B 13-10, B 13-16 Battery site

Inactive | Shut-down Battery sign

CA: Battery sign needs:

A: Emergency contact number, B: Company Name,

C: PA well(s) should NOT be referenced on sign.

Include API number(s) with well names



Photo #6

Nakagawa PM B 13-10, B 13-16 Battery site

Inactive | Shut-down

CA: Crude oil tank needs:

A: Contents & Capacity Placards, NFPA label peeling.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NAKAGAWA PM B-65N64W/13NWSE

Location ID: 327101



Photo #7

Nakagawa PM B 13-10, B 13-16 Battery site

Inactive | Shut-down

Produced H₂O vault

Comment: Sign capacity label: Fading



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources