

**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Tank battery from entrance off county road**



**Sign at tank battery**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Tank battery from Southeast corner**



**Open to wildlife**



Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011



Debris



Debris



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Tank battery from Southwest corner**



**Stained soil outside of tank battery**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Stained soil outside of tank battery**




**Stained soil outside of tank battery**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Access road from tank battery**



**Access road at location**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Unstable slope**



**Debris**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**




**Water tank and berm**



**Wellhead leaks. Stained soil**



Robert L Bayless Producer LLC  
Zimmerman/Chamberlain 1  
Loc ID: 313011




Debris



Leaking equipment



Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011



**Stained soil**



**Equipment leaks. Stained soil**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Leaking equipment**



**Personal storage**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Disconnected lines open to wildlife**



**Personal storage**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Personal storage**



**Sediment migration**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Debris**



**Unused equipment**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Sediment migration.**




**Sediment migration**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Sediment migration**



**Debris**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Open to wildlife**



**Sediment migration.**



Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011



**Sediment migration.**



**Debris**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Open to wildlife**



**Personal storage**



Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011



Personal storage



Not in use. Unused equipment.



Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011



**Not in use. Unused equipment.**



**Debris**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Weed growth**



**Weed growth**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Location from Southeast corner**



**Location from Southwest corner**



**Robert L Bayless Producer LLC  
Zimmerman/Chamberlin 1  
Loc ID: 313011**



**Location from Northwest corner**



**Location from Northeast corner**