

Inspection Photos
Location Name: Bledsoe 12-26-5-45
API Number: 125-09717



1. Sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Bledsoe 12-26-5-45
API Number: 125-09717




3. Concrete Pad and production related debris. Note vegetation growth.



4. View of Gas Meter inside Meter Shed.

Inspection Photos
Location Name: Bledsoe 12-26-5-45
API Number: 125-09717



5. View of Chart inside Meter Box at time of inspection.

Omimex Meter Test Report

Well Name Bledsoe 12-26-5-45 Date 7-17-20

Diff. Range 0 to 100 Piston 250

Static Range 0 to 100

Temp Average 60

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (150)	75	75 (150)
0	0	0

Inspector [Signature]

2023.08.02 12:46

6. View of Meter Calibration/Test Log located inside Meter Shed.

Inspection Photos
Location Name: Bledsoe 12-26-5-45
API Number: 125-09717



7. Location overview.



8. Vegetation growing inside the stock panel fencing.