

**TEP**  
**GV 42-6**  
**Location ID:**  
**334957**



## Tank battery



## Tank battery sign fading



TEP  
GV 42-6  
Location ID:  
334957



Well heads



Well heads



TEP  
GV 42-6  
Location ID:  
334957



Access road



Gully erosion in ditch



**TEP**  
**GV 42-6**  
**Location ID:**  
**334957**



## Open cellars full of fluid



## Erosion



TEP  
GV 42-6  
Location ID:  
334957



**Sediment trap with sediment running over**



**Sediment trap with sediment running over**



TEP  
GV 42-6  
Location ID:  
334957



**Sediment migration choking out vegetation**



**Sediment migration choking out vegetation**



TEP  
GV 42-6  
Location ID:  
334957



**Sediment migration**



**Sediment migration**





TEP  
GV 42-6  
Location ID:  
334957



**Sediment migration**



**Sediment migration**



TEP  
GV 42-6  
Location ID:  
334957



**Inlet of culvert under sediment**



**Outlet of culvert under sediment**