

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad
Location ID: 335151



Location Overview: Location is within High Priority Habitat area & Bald Eagle Roost site & in close proximity to Density habitat area & Bald Eagle Nest site. Location is approximately 700 yards from the Colorado River.

Section/Township/Range: 28 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad
Location ID: 335151



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad
Location ID: 335151



Photo #3814 From inspection 708900191 conducted on 03/30/2023 Erosion & transport of sediment



Photo # 4606 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad
Location ID: 335151



Photo # 4609 Erosion & transport of sediment



Photo # 4610 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad
Location ID: 335151



Photo # 3820 From inspection 708900191 conducted on 03/30/2023 Erosion & transport of sediment off location onto lease road/insufficient run on/run off controls/BMP's



Photo # 4612 Erosion & transport of sediment off location onto lease road/insufficient run on/run off controls/BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad
Location ID: 335151



Photo # 4615 Erosion & transport of sediment off location onto lease road/insufficient run on/run off controls/BMP's



Photo # 4617 Erosion & transport of sediment off location onto lease road/insufficient run on/run off controls/BMP's