

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 4592 From entrance to location



Photo # 4593 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 4596 Location



Photo # 4597 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 4598 Location



Photo # 4618 Open cellar/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 4619 Open cellar/wildlife hazard