


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 139-21 Pad
Location ID: 335174




**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 21 6S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 139-21 Pad
Location ID: 335174



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 139-21 Pad
Location ID: 335174



Photo # 4544 Check dam needs maintenance (S/SE area of location & road)



Photo # 4545 Check dam needs maintenance (S/SE area of location & road)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 139-21 Pad
Location ID: 335174



Photo # 4546 Check dam needs maintenance (S/SE area of location & road)



Photo # 4549 Sediment trap needs maintenance/tunnel erosion (S/SW area of location down from the check dams)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 139-21 Pad
Location ID: 335174



Photo # 4550 Sediment trap needs maintenance/tunnel erosion (S/SW area of location down from the check dams)



Photo # 4552 Sediment trap needs maintenance/tunnel erosion (S/SW area of location down from the check dams)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 139-21 Pad
Location ID: 335174



**Photo # 4550 Sediment trap needs maintenance/tunnel
erosion (S/SW area of location down from the check dams)**