

Inspection Photos
Location Name: Wildhorse 16-13L SWD
Location ID: 432960



Photo 1 – Signs at Entrance



Photo 2 – Tanks

Inspection Photos
Location Name: Wildhorse 16-13L SWD
Location ID: 432960



Photo 3 – Crude Oil Tanks



Photo 4 – Tanks

Inspection Photos
Location Name: Wildhorse 16-13L SWD
Location ID: 432960



Photo 5 – Tanks



Photo 6 – Unused Supply and Parts in NE Corner of Location

Inspection Photos
Location Name: Wildhorse 16-13L SWD
Location ID: 432960



Photo 7 – Unused Supply and Parts in NE Corner of Location



Photo 8 – Weeds on East of Location

Inspection Photos
Location Name: Wildhorse 16-13L SWD
Location ID: 432960



Photo 9 – Weeds on East of Location



Photo 10 – Trash

Inspection Photos
Location Name: Wildhorse 16-13L SWD
Location ID: 432960



Photo 11 – Unused Parts/Storage of Supply on North Side of Location



Photo 12 – Tanks

Inspection Photos
Location Name: Wildhorse 16-13L SWD
Location ID: 432960



Photo 13 – Stained Soil and Oily Waste at Truck Load Outs



Photo 14 – Stained Soil and Oily Waste at Truck Load Outs